7 tons, respectively. Since the Castle Hayne monitor observed SO<sub>2</sub> concentrations well below the 1-hour SO<sub>2</sub> standard, the NCDENR believes that it is reasonable to exclude this portion of New Hanover County.




Figure 3. Monitor and Source Locations in New Hanover County

## **Emissions-Related Data**

The top ten SO<sub>2</sub> emitting facilities in New Hanover County are listed in Table 2 below. The emissions reported in Table 2 are for 2009 except for National Gypsum and Vopak Terminal. For these two sources, the last reported emissions are included in the table. Five of the top ten emitters are located in the North Carolina recommended nonattainment area and these account for 98 percent of New Hanover County's total SO<sub>2</sub> emissions (Figure 4). Additionally, the NCDENR looked at sources located in Brunswick and Pender Counties. There are two large SO<sub>2</sub> sources located in Brunswick County: DAK America with 2,167 tons of SO<sub>2</sub> per year and CPI